



WAREHOUSE MATRIX

A.B.N 29 764 742 043

PO Box 24
Balaklava SA 5461

Telephone 08 8862 2078
Facsimile 08 8862 2033

SCHEDULE FOR TREATMENT AND MAINTENANCE OF CORK FLOORING

1. Preparation of New Floor

24 hours after a cork tiled floor has been laid it should be fine sanded if the tiles are uneven. The surface must be dry and free from wax, grease and dust.

After the floor has been sanded use a vacuum cleaner to pick up dust - do not use damp rags or a mop to remove dust.

Apply Surface Seal S.2

2. First Coat of Seal - S-2

Apply one coat Peerless Surface Seal S-2 using a brush or lambs-wool applicator.

A thin even coat gives the best results. Make sure that no pools of excess seal are left on the floor. Allow floor to dry for six to eight hours or preferably overnight.

3. Cut back the surface with a No. 1 (Medium Grade) Steel wool pad under a slow speed single brush floor machine or a 12" x 6" steel wool pad under an applicator.

Sweep and vacuum thoroughly to remove all dust.

4. Apply two coats of Peerless Super Finish Seal S.4.

Apply in a similar manner to the first coat of seal. Allow to dry six to eight hours or preferably overnight before applying the final coat of Super Finish Seal S.4. Allow 72 hours before subjecting the floor to heavy traffic.

OLD SURFACES

In the re-coating of cork tiled floors with Peerless Super Finish Seal S.14. It is important that the floor surface be thoroughly prepared by:

(a) Remove any type of floor polish with Peerless Floor Stripping Emulsion ST-9 used in accordance to the directions on label.

(b) Cut the surface back with a sand screen disc 100 grit or sandpaper.

(c) Sweep and vacuum thoroughly to remove all dust.

(d) Apply 2 coats of Super Finish Seal S.4 allowing over night to dry between coats.

Note: The brush or lambs-wool applicator should be washed with mineral turpentine immediately after use.

Coverage: One litre of Peerless Super Finish Seal covers 10 - 12 sq.mt.

MAINTENANCE OF CORK FLOORING

To protect areas from damage by hard sole shoes, apply two coats of Peerless Supreme WE.45 with a clean cotton mop or lambs-wool applicator. Allow one hour drying time between coats. Re-coat heavy traffic areas as required.

Where cleaning is necessary, mop with Peerless Sleek LC.50 in accordance to the directions on the label.

In a domestic area where a machine buffing wax polish is required, use Peerless Heavy Duty Duraglo to coat the floor and maintain with a wax based cleaner



Main Office: 27 Gwy Terrace, Balaklava SA 5461
Email: info@warehousematrix.com.au